

Building and Project Description

| | | |
|---|-----------|-------------------|
| Sheffield HSMS | \$ | 6,125,000 |
| 98 Classroom Ventilation Improvements - Variable Refrigerant Flow System Replacement | \$ | 3,210,000 |
| Gymnasium and Locker Room Ventilation Improvements - New Air Handling Units | \$ | 1,399,000 |
| Library Ventilation Improvements - Air Handler Replacement | \$ | 93,000 |
| Office Ventilation Improvements - Rooftop Unit Replacement | \$ | 166,000 |
| Roof Replacement (2026) - Sections 1, 2, & 3 | \$ | 835,000 |
| Secure Entrance | \$ | 255,000 |
| Upgrade Electrical Distribution System | \$ | 167,000 |
| Rockwell ES | \$ | 10,102,950 |
| Asbestos Abatement 1930s and 1950s | \$ | 339,000 |
| District Office Ventilation Improvements - Rooftop Unit Replacement | \$ | 150,000 |
| Domestic Water Piping Replacement | \$ | 334,000 |
| Elementary Roof Replacement (2025) - Sections 3, 6, 10 & 14 | \$ | 738,950 |
| Gymnasium Ventilation Improvements - Air Handling Unit Replacement with Dehumidification | \$ | 1,154,000 |
| Two Story Classroom Ventilation Improvements - Variable Refrigerant Flow System Replacement | \$ | 2,730,000 |
| Upgrade Electrical Distribution System | \$ | 267,000 |
| West Classroom Ventilation Improvements - Variable Refrigerant Flow System Replacement | \$ | 4,390,000 |
| Grand Total | \$ | 16,227,950 |

\$16,277,950

HS – Sheffield Campus

- E.1 – Upgrade Electrical Distribution System – 1998 Addition
- EXT.1 – Roof Replacement – Sections 1, 2, & 3
- M.1 – 98 Classroom Ventilation Improvements – Variable Refrigerant Flow System Replacement
- M.2 – Office Ventilation Improvements – Rooftop Unit Replacement
- M.3 – Library Ventilation Improvements – Air Handler Replacement
- M.4 – Gymnasium and Locker Room Ventilation Improvements – Air Handling Units
- PROG.1 – Secure Entrance

ES – Rockwell Campus

- E.1 – Upgrade Electrical Distribution System – Remaining building sections
- EXT.3 – Elementary Roof Replacement – Sections 3, 6, 10, & 14
- HAZ.1 – Asbestos Abatement 1950 building addition
- M.5 – West Classroom Ventilation Improvements – Variable Refrigerant Flow System Replacement
- M.6 – Two Story Classroom Ventilation Improvements - Variable Refrigerant Flow System Replacement
- M.7 – District Office Ventilation Improvements – Rooftop Unit Replacement
- M.8 – Gymnasium Ventilation Improvements – Air Handling Unit Replacement with Dehumidification
- P.1 – Domestic Water Piping Replacement